## ABBREVIATION FOR NOZZLES ON PROCESS <u>EQUIPMENT</u>

NOZZLE SYMBOL	DESCRIPTION
A , A1 , A2	INLETS
В	OUTLET
С	DRAIN OR DRAW OFF
D	DRAIN
E ( * )	
F	FEED
G	LEVEL GAUGE OR GAUGE GLASS
Н	HANDHOLES
J	PUMPOUT
K ( *)	
L	LEVEL INSTRUMENT (ALSO LT , LI)
M	MANHOLE
N	REBOILER CONNECTION
Р	PRESSURE CONNECTION (ALSO PT ,PI)
R	REFLUX
S	STEAM OR SAMPLE CONNECTION
Т	TEMPERATURE CONNECTION (ALSO TI ,TE,TW)
V	VAPOR OR VENT
W	RELIEF VALVE CONNECTION (OVERSIZE UNLESS ACTUAL SIZE KNOWN)

<sup>\*</sup> USE E OR K WHEN NON OF THE OTHER SYMBOLS APPLY. DO NOT USE I, O, Q, U, X, Y OR Z.